

Client Logo	COMPANY NAME PLANT NAME QA Department	
--------------------	--	--

Data Log

Department	DEPARTMENT NAME			
Filter From	08-Nov-2022 17:05	Filter To	08-Nov-2022 17:30	
Records From	08-Nov-2022 17:05	Records To	08-Nov-2022 17:29	
Equipment	CRH Scanner 12 CH			
Temperature	Low Alarm	0.0	High Alarm	0.0
Humidity %RH	Low Alarm	0.0	High Alarm	0.0

Channel Name	CH	Minimum	Maximum	Average
Temperature	CH1	25.7	25.7	25.70
Temperature1	CH2	0	0	0.00
Temperature2	CH3	0	0	0.00
Temperature3	CH4	0	0	0.00
Temperature4	CH5	0	0	0.00
Temperature5	CH6	0	0	0.00
Temperature6	CH7	0	0	0.00
Temperature7	CH8	0	0	0.00
Temperature8	CH9	0	0	0.00
Temperature9	CH10	0	0	0.00
Temperature10	CH11	0	0	0.00
Temperature11	CH12	0	0	0.00
Temperature12	CH13	0	0	0.00

Channel Name	CH	Minimum	Maximum	Average
Humidity	CH1	75.9	75.9	75.90
Humidity1	CH2	0	0	0.00
Humidity2	CH3	0	0	0.00
Humidity3	CH4	0	0	0.00
Humidity4	CH5	0	0	0.00
Humidity5	CH6	0	0	0.00
Humidity6	CH7	0	0	0.00
Humidity7	CH8	0	0	0.00
Humidity8	CH9	0	0	0.00
Humidity9	CH10	0	0	0.00
Humidity10	CH11	0	0	0.00
Humidity11	CH12	0	0	0.00
Humidity12	CH13	0	0	0.00

Client Logo

COMPANY NAME

PLANT NAME

QA Department



Data Log

Department	DEPARTMENT NAME			
Filter From	08-Nov-2022 17:05	Filter To	08-Nov-2022 17:30	
Records From	08-Nov-2022 17:05	Records To	08-Nov-2022 17:29	
Equipment	CRH Scanner 12 CH			
Temperature	Low Alarm	0.0	High Alarm	0.0
Humidity %RH	Low Alarm	0.0	High Alarm	0.0

Sr. No.	Log Date	Log Time	Temp SV	Temp PV	CH1	CH2	CH3	CH4	CH5	CH6	CH7	CH8	CH9	CH10	CH11	CH12
			RH SV	RH PV	CH1	CH2	CH3	CH4	CH5	CH6	CH7	CH8	CH9	CH10	CH11	CH12
1	08-Nov-2022	17:05	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
2	08-Nov-2022	17:06	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
3	08-Nov-2022	17:07	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
4	08-Nov-2022	17:08	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
5	08-Nov-2022	17:09	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
6	08-Nov-2022	17:10	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
7	08-Nov-2022	17:11	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
8	08-Nov-2022	17:12	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
9	08-Nov-2022	17:13	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
10	08-Nov-2022	17:14	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
11	08-Nov-2022	17:15	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
12	08-Nov-2022	17:16	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0

FOOTER NOTE

Client Logo

COMPANY NAME

PLANT NAME

QA Department



Data Log

Department	DEPARTMENT NAME															
Filter From	08-Nov-2022 17:05					Filter To	08-Nov-2022 17:30									
Records From	08-Nov-2022 17:05					Records To	08-Nov-2022 17:29									
Equipment	CRH Scanner 12 CH															

Temperature	Low Alarm	0.0	High Alarm	0.0
Humidity %RH	Low Alarm	0.0	High Alarm	0.0

Sr. No.	Log Date	Log Time	Temp SV	Temp PV	CH1	CH2	CH3	CH4	CH5	CH6	CH7	CH8	CH9	CH10	CH11	CH12
			RH_SV	RH_PV	CH1	CH2	CH3	CH4	CH5	CH6	CH7	CH8	CH9	CH10	CH11	CH12
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
13	08-Nov-2022	17:17	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
14	08-Nov-2022	17:18	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
15	08-Nov-2022	17:19	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
16	08-Nov-2022	17:20	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
17	08-Nov-2022	17:21	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
18	08-Nov-2022	17:22	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
19	08-Nov-2022	17:23	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
20	08-Nov-2022	17:24	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
21	08-Nov-2022	17:25	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
22	08-Nov-2022	17:26	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
23	08-Nov-2022	17:27	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0

Client Logo

COMPANY NAME

PLANT NAME

QA Department



Data Log

Department	DEPARTMENT NAME			
Filter From	08-Nov-2022 17:05	Filter To	08-Nov-2022 17:30	
Records From	08-Nov-2022 17:05	Records To	08-Nov-2022 17:29	
Equipment	CRH Scanner 12 CH			
Temperature	Low Alarm	0.0	High Alarm	0.0
Humidity %RH	Low Alarm	0.0	High Alarm	0.0

Sr. No.	Log Date	Log Time	Temp SV	Temp PV	CH1	CH2	CH3	CH4	CH5	CH6	CH7	CH8	CH9	CH10	CH11	CH12
			RH_SV	RH_PV	CH1	CH2	CH3	CH4	CH5	CH6	CH7	CH8	CH9	CH10	CH11	CH12
24	08-Nov-2022	17:28	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
25	08-Nov-2022	17:29	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
26	08-Nov-2022	17:05	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
27	08-Nov-2022	17:06	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
28	08-Nov-2022	17:07	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
29	08-Nov-2022	17:08	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
30	08-Nov-2022	17:09	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
31	08-Nov-2022	17:10	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
32	08-Nov-2022	17:11	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
33	08-Nov-2022	17:12	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
34	08-Nov-2022	17:13	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
35	08-Nov-2022	17:14	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0

FOOTER NOTE

Client Logo

COMPANY NAME

PLANT NAME

QA Department



Data Log

Department	DEPARTMENT NAME			
Filter From	08-Nov-2022 17:05	Filter To	08-Nov-2022 17:30	
Records From	08-Nov-2022 17:05	Records To	08-Nov-2022 17:29	
Equipment	CRH Scanner 12 CH			
Temperature	Low Alarm	0.0	High Alarm	0.0
Humidity %RH	Low Alarm	0.0	High Alarm	0.0

Sr. No.	Log Date	Log Time	Temp SV	Temp PV	CH1	CH2	CH3	CH4	CH5	CH6	CH7	CH8	CH9	CH10	CH11	CH12
			RH_SV	RH_PV	CH1	CH2	CH3	CH4	CH5	CH6	CH7	CH8	CH9	CH10	CH11	CH12
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
36	08-Nov-2022	17:15	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
37	08-Nov-2022	17:16	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
38	08-Nov-2022	17:17	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
39	08-Nov-2022	17:18	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
40	08-Nov-2022	17:19	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
41	08-Nov-2022	17:20	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
42	08-Nov-2022	17:21	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
43	08-Nov-2022	17:22	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
44	08-Nov-2022	17:23	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
45	08-Nov-2022	17:24	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
46	08-Nov-2022	17:25	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0

FOOTER NOTE

Client Logo

COMPANY NAME

PLANT NAME

QA Department



Data Log

Department	DEPARTMENT NAME			
Filter From	08-Nov-2022 17:05	Filter To	08-Nov-2022 17:30	
Records From	08-Nov-2022 17:05	Records To	08-Nov-2022 17:29	
Equipment	CRH Scanner 12 CH			
Temperature	Low Alarm	0.0	High Alarm	0.0
Humidity %RH	Low Alarm	0.0	High Alarm	0.0

Sr. No.	Log Date	Log Time	Temp SV	Temp PV	CH1	CH2	CH3	CH4	CH5	CH6	CH7	CH8	CH9	CH10	CH11	CH12
			RH_SV	RH_PV	CH1	CH2	CH3	CH4	CH5	CH6	CH7	CH8	CH9	CH10	CH11	CH12
47	08-Nov-2022	17:26	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
48	08-Nov-2022	17:27	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
49	08-Nov-2022	17:28	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0
50	08-Nov-2022	17:29	28.0	25.7	0	0	0	0	0	0	0	0	0	0	0	0
			75.0	75.9	0	0	0	0	0	0	0	0	0	0	0	0